


KIT SHOULD INCLUDE

(2) - SWIVEL CASTER



(4) - 1/2-13 UNC x 1 1/2"
BOLT, WASHER, & LOCKWASHER
(FOR USE ON SWIVEL CASTER)



Material
HANDLING .COM

materialhandling.com | 855.719.1415 | sales@materialhandling.com

Powered by Premier Handling Solutions, Inc.


1415 Davis Rd Elgin, IL 60123

MaterialHandling.com

-P-CKIT CASTER KIT

INSTRUCTIONS:

1. DRILL HOLES IN THE LOCATIONS SHOWN BELOW IN THE CYLINDER CADDY BASE PAN. (NOTE: HOLES NEEDED ON BOTH SIDES OF THE UNIT)
2. MOUNT SWIVEL CASTER ASSEMBLY ON ENDS OF UNIT



PROPRIETARY AND CONFIDENTIAL
THE INFORMATION CONTAINED IN THIS
DRAWING IS THE SOLE PROPERTY OF
VESTIL MANUFACTURING CO. ANY
REPRODUCTION IN PART OR AS A WHOLE
WITHOUT THE WRITTEN PERMISSION OF
VESTIL MANUFACTURING CO. IS
PROHIBITED.

UNLESS OTHERWISE SPECIFIED:

REMOVE ALL BURRS AND SHARP EDGES

DIMENSIONS ARE IN INCHES

CONCENTRIC .006 TIR .060 TIR

ANGLES ± 0° 30' ± 1° 0'

DECIMALS x.xxx ± .005

x.xx ± .010

FRACTIONS ± 1/32 ± 1/16

TOLERANCES MACHINE WELDMENT

COMMENTS:

DO NOT SCALE DRAWING

Vestil Manufacturing Co.

DESCRIPTION:

INSTRUCTIONS, CYL-P-CKIT

DRAWN BY:
K. YOUNG

DATE:
9/12/05

SCALE: 1:6

SIZE
A

CHECKED BY:

DATE:

SHEET 1 OF 1

MATERIAL

DWG. NO.
33-126-007

REV